Approved For Release 2002/06/13 CIA	
Lockheed Aircraft Corp. CHANGE	PROPOSAL X
DATE 4-6-59 AFFECTS	WSPO X PROJECT X
NAME OF MAJOR COMPONENT PART OR LOWEST Q=198 & Q=207 Kit Assems. Handle As	The state of the s
TITLE OF PROPOSAL: Emergency Oxygen Release Assembly - Automatic & Manual	
NATURE OF PROPOSAL: Furnish new handle assembly (green apple) with button type fastener for attaching to cable housing. Ref: Firewell Service Bulletin No. 6.	
NOTE: LAC does not concur in the need for this change. To our knowledge there has never been an occasion when the condition stated under "Purpose" has occurred. If the change is approved, it will be issued as an LAC Bulletin, not as a Firewel Bulletin.	
REASON FOR PROPOSAL:	
possibility of handle being accidently pulled during handling, thereby exhausting the emergency oxygen supply. ESTIMATED COST AND TIME INVOLVED:	
ADDITIONAL FUNDING REQUIRED : -	
ESTIMATED COST FOR KITS OR PARTS : \$5.00	68.
CP ADDITIONAL FUNDING REQUIRED : None (SP-1917)	
ITEMS AFFECTED BY PROPOSAL :	-
EFFEC ANCE PROCEDURE CHANGE WEIG	HIT OR TOOLS & MAINTE- SERVICE SUPPORT NANCE PROCEDURE PROCEDURE NANCE MANUAL
EST. MAN/HRS. REQ'D. TO ACCOMPLISH CHANGE IN	FIELD 1 hr.
SOURCE OF PARTS FOR KIT LAC	AVAILABILITY 14 WEEKS AFTER APPROVAL
DISPOSITION OF SPARES AFFECTED . Scrap	STATINTL STATINTL
INITIATED BY: Firewel TO SERVED TO SERVED	APPROVED: WSPO
	PROJECT PROJECT PAGE 1 OF 1